













序号	漏水点	附图1
1	三楼百度：泛兰州办公室玻璃幕墙、石材幕墙渗漏水。	
2	三楼百度：玉梅令办公室玻璃幕墙、石材幕墙渗漏水。	
3	三楼百度：大办公室、大厦正右边办公室玻璃幕墙、石材幕墙渗漏水。	
4	三楼百度：茶水间玻璃幕墙、石材幕墙渗漏水。	

5	百度：水龙岭办公室玻璃幕墙、石材幕墙渗漏水。	 A photograph of an office window with dark curtains. A red rectangular box is drawn over the window frame and glass, indicating a leak area. The view outside shows a tall building.
6	科医能总经理办公室玻璃幕墙、石材幕墙渗漏水。	 A photograph of a curved office window. A red rectangular box is drawn over the window frame and glass, indicating a leak area. The view outside shows a tall building.
7	3楼靠背面通道外幕墙渗水，玻璃幕墙、石材幕墙渗漏水。	 A photograph of an office window. A red rectangular box is drawn over the window frame and glass, indicating a leak area. The view outside shows a tall building.
8	8楼超开心酒业洽谈室外幕墙渗水，玻璃幕墙渗漏水。	 A photograph of an office window. A red rectangular box is drawn over the window frame and glass, indicating a leak area. The view outside shows a tall building.
9	8楼超开心会客室外幕墙渗水，玻璃幕墙渗漏水。	 A photograph of an office window. A red rectangular box is drawn over the window frame and glass, indicating a leak area. The view outside shows a tall building.

10	12楼溢丰华创茶水间外幕墙渗水。 。	
11	10楼溢丰华创会议室外幕墙渗水。 。	
12	13楼世纪证卷大会议室外幕墙渗水。	
13	16楼中信银行领导办（2个）公室大厦正面角边外幕墙渗水。	
14	16楼中信银行副行长办公室大厦正面角边外幕墙渗水。	

15	16楼中信银行接待室外幕墙渗水，玻璃幕墙渗漏水。	
16	16楼中信银行临时办公室外幕墙渗水。	
17	4楼平台墙根渗水进办公室地面防水维修	